

Basic Vehicle Condition Guide

Report ID: 18,837,720


Version: 4

Created: 21 Dec 2018

Make: Model: Ford Courier **Body Style:** Utility Year: 2005 Registration: CTQ3 Reg Expiry: 18 Jan 2019 WoF Expiry: **Odometer:** 21 Jan 2019 144,135 Kms **Good No:** 18837720 VIN: MNALS2D705W45901 Next Service: **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Engine oil leaks Service Due

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Dion Mair Date: 30 Nov 2018

Name:

	Pass	Fail	N/A
Engine	•		
Oil level		~	
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System	•	•	
Coolant condition		~	
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•		
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	1		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	3.0 mm		
Right front	3.0		mm
Left rear	4.0		mm
Right rear	4.0		mm
Spare	Yes		
Suspension	ı		
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	1		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			1

Signature: