

Report ID: 18,838,165 Version: 1 03 Dec 2018 Created:

Make:	Nissan	Model:	Wingroad	Body Style:	Wagon		Pass	Fail	N/A
Year:	2008		HAA12	Reg Expiry:	Magon	Engine	1 455		
	16 Nov 2019	Odometer:	169,271 Kms	Good No:	18838165	Oil level	~		
VIN:	7AT0DH5GX13097650		100,27114115	Service History		Smoke & fumes	~		
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				110	Performance	~		
	port is not a warranty					Noise	v v		
	a guide only. Conside						V		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
						Coolant condition Performance	~		
Key:		-0	S S		S		~		
S = scratch	re	A(U)	<u>C</u>	all'E	~	Radiator / Hoses (visual)	~		
D = dent					HID	Transmission			<del></del>
R = rust				10	HILY	Operation	~		
PT = paint defe	ect M				S SC	Noise	~		<u> </u>
C = crack	III					Clutch			~
P = pin dent * = decals	dic				THE	CV joints	~		<u> </u>
SC = stone chi		10		10		Wheel bearings	~		
W = significant scuffs						Brakes			
			S S			Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Front bumper misaligned						Tyres (lowest observed tread depth of tyres)			
Key remote not working LH tail lamp cracked, water entry						Left front	2 mm		
	Clacked, water entry					Right front		2	mm
						Left rear		2	mm
Conditions During Body Inspection: Dry						Right rear	2 mm		
						Spare Yes			
<u>Under Ca</u>	rriage & Under Bor	net Inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		1
						Operation	~		Τ
Interior Comments						Electrical / Accessories	1	1	4
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Avelage					Indicators	V		
Panels	Average					Dashboard warning lights	~		+
						Wipers (front & rear)	~		+
Dashboa	rd Good					Window winder FL	~		+
						Window winder FR	~		+
General Comments					Window winder RL	~		+	
FL power window not working from door switch					Window winder RR	~		+	
						Rear view mirrors	~		+
						Radio (basic test only)	~		+
						CD (basic test only)	v v		+
						Number of keys	2		1
						Central locking	2 V		
Road Conditions During Test Drive: Wet							~		
Engine Tir	ning Mechanism:	Timing	Chain			Remote locking		~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Lindence						Reversing camera			~
Inspected	d by: Mathew Varghe	se				Date: 03 Dec 20	18		
·`									

I have read and understood this condition guide.

Name: .....

Signature: .....