

Report ID: 18,838,448 Version: 1 Created: 07 Dec 2018

Make:	Holden	Model:	Еріса	Body Style:	Sedan		Pass	Fail	N/A
Year:	2011		KLZ10	Reg Expiry:	28 Feb 2019	Engine			<u> </u>
WoF Expiry:		Odometer:	127,691 Kms	Good No:	18838448	Oil level	~		1
VIN:	KL3LA69RJAB062938	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		6	Danta hava nat	harry discovered and an	Noise	~		+
	a guide only. Conside sting undertaken. The					Cooling System	•		
	ical inspection prior to					Coolant condition	~		1
						Performance	~		
Key:	s w	-0	SP		S	Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
D = dent	sw 6/6			The	BID SD	Operation	~		1
R = rust				10	THIA	Noise	~		
PT = paint def C = crack				+	S SC	Clutch	•		~
P = pin dent	Ho					CV joints	~		
* = decals	S PT SC			AL-	ENR	Wheel bearings	-		
SC = stone chips						Brakes	~		
W = significant scuffs S P S S W S						Performance			
		Noto: com				Hand Brake	v		+
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							~	- (-	
Stone chips front screen.						Tyres (lowest observed tread depth of tyres)			
						Left front		5	mm
						Right front		5	mm
						Left rear	6		mm
Conditions During Body Inspection: Dry						Right rear	6		mm
Under Carriage & Under Pernet Inspection Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
FWD.						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u> Front screen wiper blade loose.Radio code required.						Window winder RL	~		
Front scree	n wiper blade loose.Rac	lio code requirec	l.			Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)		~	
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
			-			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Less este d'har. Estelle Mersteur									
Inspected by: Eddie Marsters Date: 07 Dec 2018									
I have read	and understood th	is condition a	uide. Name:			Signature:			