

Basic Vehicle Condition Guide

Report ID: 18,840,282


Version: 1

Created: 10 Dec 2018

Make: Model: Nissan Primera **Body Style:** Sedan Year: 2002 Registration: **FUS309** Reg Expiry: 05 Jul 2019 WoF Expiry: **Odometer:** 04 Oct 2019 120,389 Kms **Good No:** 18840282 VIN: 7AT0DH2GX11008526 Next Service: 102000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

RF door mirror casing broken,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments		
Seats	wear and tear,minor stains ,	
Carpets	Average	
Panels	Average	
Dashboard	Average	

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

10 Dec 2018 Inspected by: Donovan Matara Date:

Name:

Pass	Fail	N/A
~		
~		
~		
~		
	Г	
~		
~		
~		
~		
~		
		~
~		
~		
	Т	
~		
'		
d depth	of tyre	es)
	3	mm
2		mm
7		mm
7		mm
	Yes	
	ı	
~		
~		
~		
~		
~		
~		
-		
~		
+		
~		
~		
~		
~		
~		
1		
~		
	~	
		~
~		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

Signature: