

Turners Certified Imports 50 Point Check

Report ID: 18,840,604

Version: 1

12 Dec 2018 Created:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Nissan Make: **Body Style: Sedan** Tiida Odometer: 19,640 Kms Model: 2005 7AT0DH78X18003735 VIN: Year:

Under Carriage & Under Bonnet Inspection Comments

Tidy.

General Comments

Nice tidy, low km car.


Good Seats: Good Carpets: Good Panels: Dashboard: Good


Timing Chain **Engine Timing Mechanism:** Not Applicable **Evidence of Cam Belt Replacement:**

Replaced At (odometer reading):

Dry **Road Conditions During Test Drive:**

Electrical Battery Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Reversing camera •





Inspected by: Daryll Timms



= Not applicable for this vehicle

Date: 12 Dec 2018