

Report ID: 18,841,157 Version: 1 03 Dec 2018 Created:

Make:	Hyundai	Model:	lload	Body Style:	Van		Pass	Fail	N/A
Year:	2012		GHR229	Reg Expiry:	31 Dec 2018	Engine			L
WoF Expiry:		Odometer:	114,960 Kms	Good No:	18841157	Oil level	~		
VIN:	KMFWBX7KLCU47870			Service Histor		Smoke & fumes	~		
			120033		, 110	Performance	~		-
Note: This report is not a warranty						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
		_				Performance	~		
Key:	S	-0	S SC S SC		S D SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission	V		
D = dent						Operation			1
R = rust				10		Noise	ン ン		
PT = paint def C = crack	ect III			+	S	Clutch	-		
C = Crack P = pin dent	Ho			-			~		
* = decals	s pp				SD SC	CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs S SC W S SC S SC S SC S SC						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~	6 .	Ļ
						Tyres (lowest observed tread depth of tyres)			
						Left front	4.	-	mm
						Right front	5.	-	mm
						Left rear	6.		mm
Conditions During Body Inspection: Dry						Right rear	6.	.5	mm
Under Carriage & Under Pennet Inspection Comments						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			-
No underbo	ody inspection					Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
mark drivers seat						Electrical / Accessories			
Seats	indix drive	is seat				Head lights	~		<u> </u>
Carpets	hole driver	rs floor				Tail lights	~		
	Cood					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			~
This is a 6 seater van and has been used for a commercial vehicle but is tidy for age and mileage.						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Increased by Jamie Cook						Data: 02 Dac 2019			
Inspected by: Jamie Cook Date: 03 Dec 2018									
I have read	and understood thi	is condition a	juide. Name: .			Signature:			