

Report ID: 18,841,462 Version: 3 21 Mar 2019 Created:

Year:	Mitsubishi	Model:	Pajero	Body Style:	SUV		Pass	Fail	N/A
	2007	Registration:	GYH688	Reg Expiry:	19 Apr 2019	Engine			
NoF Expiry:	31 Dec 2019	Odometer:	202,977 Kms	Good No:	18841462	Oil level	<		
/IN:	7AT0CJ08X13002597	Next Service:	?	Service Histor	V: No	Smoke & fumes	<		
						Performance	~		
	eport is not a warranty s a guide only. Consid		for age and milea	ge. Parts have not	been dismantled or	Noise	~		
diagnostic te	esting undertaken. The	vehicle has beer	n driven up to 50km	h/h from cold. The	/endor recommends	Cooling System			
a full mechar	nical inspection prior to	purchase and t	his can be arranged	for an additional o	narge.	Coolant condition	~		
	S		S		S	Performance	~		
Key:	L(B	-0		701-		Radiator / Hoses (visual)	~		
= scratch						Transmission			
) = dent = rust	s sc			215	HILS	Operation	~		
T = paint def		IT I		$\left[\left(\right) \right]$	704	Noise	~		
= crack			-	$+ \mathbb{N}$	S P	Clutch			~
e = pin dent	HIG				세비	CV joints	~		-
= decals	s 916			- NL	EIPS	Wheel bearings	~		
SC = stone chips						Brakes			
N = significant scuffs S S S S S S						Performance			
		Note: son	ne defects & blemist	nes may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram					Tyres (lowest observed tread	•	oftwr	 ><)	
Stone chips in windscreen.						Left front 5.3 mm			
									-
						Right front Left rear	5.		mm
						6.	-	mm	
Conditions During Body Inspection: Dry					Right rear	6.		mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	amage & onder boi	inet inspectio	<u>on comments</u>			Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	۲		
	Good					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Panels	, Good						~		
	ard Good					Window winder FL	-		
Panels Dashboa	ard					Window winder FL Window winder FR	~		
Panels Dashboa	ard Good								
Panels Dashboa	ard					Window winder FR	~		
Panels Dashboa	ard					Window winder FR Window winder RL	ン ン		
Panels Dashboa	ard					Window winder FR Window winder RL Window winder RR	> > >		
Panels Dashboa	ard					Window winder FR Window winder RL Window winder RR Rear view mirrors	> > > >		
Panels Dashboa	ard					Window winder FRWindow winder RLWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)	Y Y Y Y Y Y Y Y Y Y		
Panels Dashboa	Comments		Dru			Window winder FRWindow winder RLWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)Number of keys	V V V V V V V V V 2		
Panels Dashboa General (ard	t Drive:	Dry			Window winder FRWindow winder RLWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)Number of keysCentral locking	 ✓ ✓<		
Panels Dashboa General (Road Con	Comments	t Drive: Cambel	•			Window winder FRWindow winder RLWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)Number of keysCentral lockingRemote locking	V V V V V V V V V 2		
Panels Dashboa General (Road Con Engine Ti	ard Comments Comments	Cambel	•	Kms:		Window winder FRWindow winder RLWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)Number of keysCentral locking	 ✓ ✓<		

I have read and understood this condition guide.

Name:

Signature: