

	Good		
Dashboard			Window winder FL
			Window winder FR
<u>General Comments</u>			Window winder RL
Roof lining and door card falls Spongy brake			Window winder RR
opong) state			Rear view mirrors
			Radio (basic test only)
			CD (basic test only)
			Number of keys
Road Conditions During Test Drive: Dry			Central locking
			Remote locking
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:			Sat. Nav. (basic test only)
			Reversing camera
Inspected by: Bob	by Zhong		Date: 07 Dec 2
			Butter to Ette

I have read and understood this condition guide.

Name:

ate: 07 Dec 2018

Signature:

V

V

V

V

1

V

✓
2

レ レ

V

V