

Report ID: 18,841,750 Version: 1 17 Dec 2018 Created:

Make:	Nissan	Model:	Bluebird	Body Style:	Sedan	ון		Pass	Fail	N/A	
Year:	2003	<b>Registration:</b>	FKY578	<b>Reg Expiry:</b>	09 Mar 2019		Engine	•	•		
WoF Expiry:	03 Jul 2019	Odometer:	155,168 Kms	Good No:	18841750	lİ	Oil level	~			
VIN:	7AT0DH1EX10156164	Next Service:	169900	Service Histor	<b>y:</b> No		Smoke & fumes	~			
						ī	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends							Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition	~			
	S D		S		S P	٦ľ	Performance	~			
Key:		-0				lİ	Radiator / Hoses (visual)	~			
S = scratch D = dent							Transmission				
B = rust SSC DA						ļ	Operation 🖌				
PT = paint defect							Noise	~			
C = crack						ļ	Clutch			~	
P = pin dent						lł	CV joints	~			
* = decals SC 919							Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs D S							Performance	~			
Dedulmen		Note: son	ne defects & blemishes	may not be disp	blayed in the diagram		Hand Brake	~			
Body Inspection Comments						lł	Tyres (lowest observed tread depth of tyres)				
Rear bumper misaligned						lł				mm	
							Right front			mm	
						Jŀ	Left rear	-		mm	
Conditions During Body Inspection: Wat						٦ŀ	Right rear			mm	
Conditions During Body Inspection: Wet						ļ	Spare	,			
Under Carriage & Under Bonnet Inspection Comments							Suspension				
						lł	Suspension performance	~			
						lł	Steering performance	V			
						lł	Shock absorbers	· ·			
							Air Conditioning / Heater	•		L	
						ļ	Operation	~			
Interior Comments						lł	Electrical / Accessories	•		<u> </u>	
Seats	Average					lł	Head lights	~			
	<b>A</b>					lł	Tail lights	· ·			
Carpets	Average						Indicators	· ·			
Panels	Average					lł	Dashboard warning lights	· ·			
Falleis							Wipers (front & rear)	~			
Dashboa	rd Average					lł	Window winder FL	· ·			
						┛╏	Window winder FR	• •			
General Comments						]	Window winder RL	• •			
Engine tapping noise							Window winder RR	• •			
							Rear view mirrors	~			
						H	Radio (basic test only)	• •			
							CD (basic test only)	~			
							Number of keys		L	L	
Road Conditions During Test Drive: Wet						┤╎	Central locking	2			
Road Con	aitions During Test	Drive:	Wet			┨╏		<b>v</b>			
Engine Tir	ning Mechanism:	Timing	Chain			ון	Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:							Sat. Nav. (basic test only)			<b>v</b>	
	Reversing camera			~							
Inspected by: Xinghui Lin							Date: 17 Dec 2018				

I have read and understood this condition guide.

Name: .....

Signature: .....