

Report ID: 18,841,979 Version: 4 14 Feb 2019 Created:

Signature:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2014		HSC118	Reg Expiry:	26 May 2019	Engine			
WoF Expiry:		Odometer:	123,695 Kms	Good No:	18841979	Oil level	~		
VIN:	MNTVCUD40A060140	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:	SD	-0	s s		S	Radiator / Hoses (visual)	~		
S = scratch	Se	10		10c	X	Transmission	V		
D = dent	IS SC 616			The	BID SD	Operation	~		
R = rust				10	7HIX —	Noise	~		
PT = paint defe C = crack	ect M			+	SC	Clutch			
C = Crack P = pin dent	LHC	KI							~
* = decals	s sc pp					CV joints	~		
SC = stone chi	ps US			10		Wheel bearings	~		ι
W = significant scuffs						Brakes			
						Performance	~		
<u>Body Insp</u>	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		L
Rear cover hook missing						Tyres (lowest observed tread depth of tyres)			
						Left front	3		mm
						Right front	3		mm
						Left rear	2.	5	mm
Conditions During Body Inspection: Wet						Right rear	2.5 mm		mm
						Spare	Yes		
	rriage & Under Bor	nnet Inspectio	on Comments			Suspension			
Underbody	surface rust					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	1				J	Window winder FR	~		
<u>General C</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Pood Com	ditions During Tas	t Drivo:				Central locking	2 V		
Road Con	ditions During Test	t Drive:	Wet			Remote locking	~		
Engine Tir	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	<i>v</i> <i>v</i>		
							-		
Inspected	d by: Xinghui Lin					Date: 14 Feb 20	19		

I have read and understood this condition guide.

Name: