

Report ID: 18,842,077 Version: 1 06 Dec 2018 Created:

Make:	Lexus	Model:	IS350	Body Style:	Sedan	1		Pass	Fail	N/A		
Year:	2005	Registration:	LSQ819	Reg Expiry: 01 Dec 2019			Engine			L		
WoF Expiry:	30 Nov 2019	Odometer:	110,817 Kms	Good No: 18842077			llevel	~				
VIN:	7AT0B00HX15002958	Next Service:		Service Histor	y: No	Sm	noke & fumes	~				
						Pe	rformance	~				
	port is not a warranty	aration is made	for and milaana	Darts have not	been dismonthed or	No	bise	~				
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System						
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition					
						Pe	rformance	~				
Key:	LS	-0	<u>s</u>	-01-		Ra	diator / Hoses (visual)	~				
S = scratch						Transmission						
D = dent R = rust	SC DI			715	HILS	Or	peration	~				
R = rust PT = paint defe				$\left(\right)$		No	bise	~				
C = crack					SC	Clu	utch			~		
P = pin dent	110				세비	CV	/ joints			~		
* = decals	ssc 916			The	ELD'S		heel bearings	~				
SC = stone chips							Brakes					
W = significant	t scuffs w	$\neg \varnothing$	\square			Pe	rformance	~				
Bodylag		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	На	and Brake	~				
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)						
						l ⊢				mm		
						Ric	ght front	3		mm		
						Le	ft rear	2		mm		
Conditions During Body Inspection: Wet						Rig	Right rear		2 mm			
	is building body ins		Wet			Sp	Spare Yes					
Under Carriage & Under Bonnet Inspection Comments						Suspension						
						Su	spension performance	~				
						Ste	eering performance	~				
						Sh	ock absorbers	~				
						Air	Conditioning / Heater			L		
							peration	~				
Interior Comments						Electrical / Accessories						
Seats	Good					He	ead lights	~				
	Good					Та	il lights	~				
Carpets	0000					Inc	dicators	~				
Panels	Average					Da	ashboard warning lights	~				
	, Good						ipers (front & rear)	~				
Dashboa	rd					Wi	indow winder FL	~				
	1					Wi	indow winder FR	~				
General Comments						Wi	indow winder RL	~				
						Wi	indow winder RR	~				
						Re	ar view mirrors	~				
						Ra	dio (basic test only)	~				
) (basic test only)	~				
						Number of keys 2						
Road Con	ditions During Test	t Drive:	Wet			. —	entral locking	~				
						Re	mote locking	~				
Engine Timing Mechanism: Timing Chain						Sa	t. Nav. (basic test only)			~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Re	eversing camera	~				
Inspected	Inspected by: Xinghui Lin							Date: 06 Dec 2018				

I have read and understood this condition guide.

Name:

Signature: