

Basic Vehicle Condition Guide

Report ID: 18,842,728


Version: 1

Created: 14 Dec 2018

Make: Model: Mazda Atenza **Body Style:** Hatchback Year: 2008 Registration: LLR855 Reg Expiry: 20 Apr 2019 WoF Expiry: **Odometer:** 03 Nov 2019 109,801 Kms **Good No:** 18842728 VIN: 7AT0C139X15100090 Next Service: 119263 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Crack back left tail light

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

No underbody inspection

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Lindsay Munro Date: 14 Dec 2018

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	ر ر		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	4	.7	mm
Right front	4.6		mm
Left rear	5.2		mm
Right rear	6.5		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V V V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR			
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

Signature: