

Basic Vehicle Condition Guide

Report ID: 18,842,856


Version: 1

Created: 18 Dec 2018

Make: Model: Mitsubishi Diamante **Body Style:** Sedan Year: 2003 Registration: BMC180 Reg Expiry: 01 Apr 2019 **Odometer:** WoF Expiry: 07 Dec 2019 180,004 Kms **Good No:** 18842856 VIN: 6MMTL8D423T00119: Next Service: 186229 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips front screen.Both headlight lens dirty.Scratch mark right hand lens.Right front gaurd n bumper miss align.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

FWD.Engine oil leak.

| Interior Comments | | | |
|-------------------|---|--|--|
| Seats | Good n Drivers seat sign of wear n marks. | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Inspected by:

Drivers door missing handle cover.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

> 18 Dec 2018 Date:

| | Pass | Fail | N/A | | |
|------------------------------|--|---------|-----|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | \(\triangle \) | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | | |
| Left front | 4. | .5 | mm | | |
| Right front | 5 | | mm | | |
| Left rear | 2.5 | | mm | | |
| Right rear | | | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | ~ | | | | |
| Wipers (front & rear) | ~ | | | | |
| Window winder FL | \(\times \) \(\t | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | · • | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | | | ~ | | |
| Number of keys | 2 | | | | |
| Central locking | ~ | | | | |
| Remote locking | | | ~ | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | | | ~ | | |
| | | | | | |

I have read and understood this condition guide.

Eddie Marsters

Name:

Signature: