

Report ID: 56,315 Version: 2 18 Jan 2019 Created:

Make:	Mercedes-Benz	Model:	ML320	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2009	Registration:	GPZ227	Reg Expiry:	29 Aug 2019	Engine				
WoF Expiry:		Odometer:	235,472 Kms	Good No:	18842943	Oil level	~			
VIN:	WDC1641222A49067(Next Service:		Service Histor	V: No	Smoke & fumes	· ·			
					-	Performance	~			
	port is not a warranty		с I I			Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~			
		_				Performance	~			
Key:	sc	-0			SP	Radiator / Hoses (visual)	~			
S = scratch D = dent						· · ·	Transmission			
						Operation V				
R = rust				10	JHIN	Noise	~			
PT = paint def C = crack	ect M			+		Clutch	V			
P = pin dent	Ho					CV joints			~	
* = decals	sc pp			AL-	ENR -	Wheel bearings	~			
SC = stone chips						J				
W = significant scuffs						Brakes				
		N				Performance	~			
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
						Tyres (lowest observed tread depth of tyres)				
						Left front	6.	.0	mm	
						Right front	6.	.0	mm	
						Left rear	3	3	mm	
Conditions During Body Inspection: Dry						Right rear	3 mm			
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
A/C not col	d					Suspension performance	~			
						Steering performance	~			
Shock absorbers							~			
						Air Conditioning / Heater				
Operation										
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Comoto	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	, Good					Wipers (front & rear)	~			
Dashboa	ra					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry Central locking							~			
			•			Remote locking	~			
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected by: DM Auto's Date: 12 Dec 2018										

I have read and understood this condition guide.

Name:

Signature: