

Basic Vehicle Condition Guide

Report ID: 56,307

Version: 1

Engine

Oil level

12 Dec 2018 Created:

Pass


Fail

N/A

Make: Model: Volkswagen Amarok **Body Style:** Utility Year: 2013 Registration: GSY600 Reg Expiry: 25 Feb 2019 WoF Expiry: **Odometer: Good No:** 19 Dec 2019 111,454 Kms 18843026 VIN: WV1ZZZ2HZDA00595 Next Service: Just Serviced **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	<u>5</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Scott

Evidence of Cam Belt Replacement: No Kms:

Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	> >		
Radiator / Hoses (visual)	'		
Transmission			
Operation	>		
Noise	~		
Clutch	ン ン ン		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	>		
Tyres (lowest observed tread	l depth	of tyre	s)
Left front	4 m		mm
Right front	4		mm
Left rear	4		mm
Right rear	4		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	/		
Air Conditioning / Heater		•	
Operation	~		
Electrical / Accessories			
Head lights	>		
Tail lights	'		
Indicators	>		
Dashboard warning lights	'		
Wipers (front & rear)	>		
Window winder FL	~		
Window winder FR	'		
Window winder RL	\(\triangle \)		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	>		
Sat. Nav. (basic test only)			~

I have read and understood this condition guide.

Name			

10 Dec 2018

Reversing camera

Date: