


<b>Make:</b>	Nissan	<b>Model:</b>	Avenir	<b>Body Style:</b>	Wagon
<b>Year:</b>	1999	<b>Registration:</b>	EJB92	<b>Reg Expiry:</b>	14 Apr 2019
<b>WoF Expiry:</b>	09 May 2019	<b>Odometer:</b>	191,984 Kms	<b>Good No:</b>	18843562
<b>VIN:</b>	7A8DH1F0708004625	<b>Next Service:</b>	200000	<b>Service History:</b>	No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key:

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



## Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Stonechips on windscreen. Damage on rear bumper. Has spare, no tools.  
Wear on steering wheel. Wear on RF seatbelt. RF seat and door card have wear.

Conditions During Body Inspection: Dry

## Under Carriage & Under Bonnet Inspection Comments

Engine has oil seepage. Surface rust under bonnet. Radiator overflow bottle lid incorrect. Coolant additive concentration below manufactures recommended level suggest coolant change. Both rear sway bar links worn. Inner edge wear both front tyres.

## Interior Comments

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

## General Comments

Turbo has whine. Excessive vibration from engine, possible engine mount.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	2	mm	
Right front	2	mm	
Left rear	3	mm	
Right rear	4	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking			✓
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Roger King

Date: 05 Dec 2018

I have read and understood this condition guide.

Name: .....

Signature: .....