

Turners Certified Imports 50 Point Check

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Nissan	Body Style:	Hatchback
Model:	Tiida	Odometer:	99,013 Kms
Year:	2010	VIN:	7AT0DH78X18366928

Under Carriage & Under Bonnet Inspection Comments

_			
	Seats:	Average	
	Carpets:	Average	
]	Panels:	Average	
	Dashboard:	Average	
]	Engine Timir	ng Mechanism:	Timing Chain

Dry

General Comments

Not Applicable **Evidence of Cam Belt Replacement:** Replaced At (odometer reading):

Road Conditions During Test Drive:

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 2.5 mm
Head lights	Noise	Smoke & fumes	Right front 2.0 mm
Tail lights	Clutch	Performance	Left rear 2.5 mm
Indicators	CV joints	Noise	Right rear 2.5 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	-	Tools
Window winder FL	Brakes	Coolant condition	Interior
Window winder FR	Drakes	Performance	Interior
	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✔= Pass¥= Fail●= Not applicable for this vehicle
Reversing camera	Number of keys 1	Inspected by: Greg Morgan	Date: 05 Dec 2018

Signature: