

Turners Certified Imports 50 Point Check

Report ID: 18,844,508

2 Version:

Created: 10 Dec 2018


Note: This report is not a warranty


This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTIFIED IMPORTED VEHICLES	iagnostic ccredited	testing undertaken I inspection agency a	n. The vehic and been tes	le has under t driven up to	gone a thorough 50km/h from cold	compliance check	by an Ni	ZTA
Make: Nissan Body Style: SUV Model: X-Trail Odometer: 109,492 Kms Year: 2009 VIN: 7AT0DH6LX18060446 Under Carriage & Under Bonnet Inspection Comments				Seats: Carpets: Panels: Dashboard:	Good Good Good Good Mechanism:	Timing Chain		
General Comments				Replaced At	Cam Belt Replacemer (odometer reading): tions During Test Drive	Wax	•	
Electrical		Transmission & Drive	•	Engine		Tyres (lowest observed)	Tyres (lowest observed tread depth)	
Battery		Operation		Oil level		Left front	4.5	m
Head lights		Noise		Smoke & fun	mes	Right front	4.5	m
Tail lights		Clutch	•	Performance		Left rear	4.5	m
Indicators		CV joints		Noise		Right rear	4.5	m
Dashboard warning lights		Wheel bearings		Cooling Sys	item .	Spare	Yes	

Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)

Reversing camera





•

Inspected by: Ca Thach

Date: 05 Dec 2018