

Report ID: 18,844,944 Version: 1 05 Dec 2018 Created:

| Make: | Toyota | Model: | Previa | Body Style: | People Mover | | Pass | Fail | N/A |
|--|---|----------------------|------------------------|--------------------|-----------------------|--|------|------|-----|
| Year: | 1994 | Registration: | SX75 | Reg Expiry: | 22 Aug 2019 | Engine | | | |
| WoF Expiry: | 14 Mar 2019 | Odometer: | 209,787 Kms | Good No: | 18844944 | Oil level | ~ | | |
| VIN: | JT711AC1001160887 | Next Service: | 218939 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty a quide only. Conside | eration is made | for age and mileage | . Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | | | | |
| a full mechan | ical inspection phor to | purchase and ti | lis can be arranged ic | | inarge. | Coolant condition | ~ | | |
| | | \sim | S | | S | Performance | ~ | | |
| Key: S = scratch | | =(0) | | 5(0)- | | Radiator / Hoses (visual) | ~ | | |
| | | | | | | Transmission | | | |
| R = rust | | | | 20 | HILLS | Operation | ~ | | |
| PT = paint defe | ect NP | | | | | Noise | ~ | | |
| C = crack | | | | TTM. | | Clutch | | | ~ |
| P = pin dent | sc de | | | | 2414 | CV joints | ~ | | |
| * = decals | | 10 | | 10 | ED S | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| W – significan | | | S S | | | Performance | ~ | | |
| Body Insr | pection Comments | Note: som | ne defects & blemishes | s may not be disp | blayed in the diagram | Hand Brake | ~ | | |
| RR lens cracked | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front 6 m | | | mm |
| | | | | | | Right front | e | 5 | mm |
| | | | | | | Left rear | e | 5 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 6 mm | | mm |
| | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| Tidy | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | 1 |
| L | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| | Average | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| | , Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ra | | | | | Window winder FL | | | ~ |
| | | | | | | Window winder FR | | | ~ |
| General Comments | | | | | | Window winder RL | | | ~ |
| | | | | | | Window winder RR | | | ~ |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | | | ~ |
| | | | | | | Number of keys | 3 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | | | ~ |
| Engine Timing Mechanism: Cambelt | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lo | Kms: | | Reversing camera | | | ~ |
| | | | | | | | | | |
| Inspected by: Stuart Melbourne Date: 05 Dec 2018 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: