

Report ID: 18,845,051 Version: 1 06 Dec 2018 Created:

Make:	Toyota	Model:	Aurion	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2009	<b>Registration:</b>	EWK186	<b>Reg Expiry:</b>	16 Mar 2019	Engine				
WoF Expiry:	02 May 2019	Odometer:	171,105 Kms	Good No:	18845051	Oil level	~			
VIN:	6T153KK400X315708	Next Service:	-	Service Histor	<b>y:</b> Yes	Smoke & fumes	~			
_						Performance	~			
	port is not a warranty a quide only Conside		for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged f	or an additional o	charge.	Coolant condition	~			
	S					Performance	~			
Key:	B	-0		500-		Radiator / Hoses (visual)	~			
S = scratch	ATE				Tan	Transmission	1		1	
D = dent R = rust	SC DE			715	HILS	Operation	~			
PT = paint defe		r I		$\left[ \left( \right) \right]$		Noise	V			
C = crack				$+ \mathbb{N}$		Clutch			~	
P = pin dent	HIC				게	CV joints	~			
* = decals	sc 916			TO		Wheel bearings	~			
SC = stone chips						Brakes	Brakes			
W = significant	t scuffs SC			JOR		Performance	~			
Dadulu	notion Comments	Note: som	ne defects & blemishe	s may not be dist	layed in the diagram	Hand Brake	~		+	
Body Insp	pection Comments			, ,	, ,	Tyres (lowest observed tread	-	oftvre	L es)	
						Left front		5	mm	
						Right front		5 5	mm	
						Left rear		, 7	mm	
Conditions During Rodulnsportion.						Right rear	7 mm			
Conditions During Body Inspection: Dry						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
	-					Suspension performance	~		1	
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	•			
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~		1	
56465						Tail lights	~			
Carpets	Good					Indicators	~		<u> </u>	
Panels	Good					Dashboard warning lights	~		┼──	
raneis						Wipers (front & rear)	~		<u> </u>	
Dashboa	rd Good					Window winder FL	~			
						Window winder FL Window winder FR				
General C	<u>Comments</u>					Window winder FR Window winder RL	<b>v</b>			
						Window winder RL Window winder RR	V 			
						Rear view mirrors	<b>v</b>		──	
							<b>v</b>		──	
						Radio (basic test only)	~		──	
						CD (basic test only)	✓ 2			
<b>D</b> 1 -						Number of keys	3			
Road Con	ditions During Test	t Drive:	Wet			Central locking	~		<u> </u>	
Engine Tir	ning Mechanism:	Timing (	hain			Remote locking	~		<u> </u>	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			<b>v</b>	
						Reversing camera			~	
Inspected	d by: Ca Thach					Date: 06 Dec 20	18			

I have read and understood this condition guide.

Name: .....

Signature: .....