

Basic Vehicle Condition Guide

Report ID: 18,845,219

Version:

Engine

Created: 10 Dec 2018


Fail

N/A

Make: Model: **Body Style:** Toyota Hilux Utility Year: 2013 Registration: HEK38 Reg Expiry: 12 Mar 2019 WoF Expiry: **Odometer: Good No:** 28 Dec 2018 167,921 Kms 18845219 VIN: MR0EZ12G504013705 Next Service: 172961 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Underbody rust

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Inspected by:

Engine vibration when cold start

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Xinghui Lin

Evidence of Cam Belt Replacement: No Kms:

| Oil level | ~ | | |
|------------------------------|---|---------|-----|
| Smoke & fumes | ~ | | |
| Performance | \(\times \) | | |
| Noise | ~ | | |
| Cooling System | | • | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | • |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | ~ | | |
| CV joints | | | ~ |
| Wheel bearings | ~ | | |
| Brakes | | • | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | depth | of tyre | es) |
| Left front | 8 | 3 | mm |
| Right front | 8 | | mm |
| Left rear | 7.5 | | mm |
| Right rear | 7.5 | | mm |
| Spare | Yes | | |
| Suspension | • | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | • | |
| Operation | ~ | | |
| Electrical / Accessories | | | • |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | VVV | | |
| Window winder FL | ~ | | |
| Window winder FR | | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | 1 |

I have read and understood this condition guide.

Name:

Signature:

10 Dec 2018

1

Reversing camera