

Report ID: 18,845,344 Version: 2 10 Dec 2018 Created:

Make:	BMW	Model:	3 Series	Body Style:	SUV		Pass	Fail	N/A	
Year:	2006	<b>Registration:</b>	LNA562	Reg Expiry:	04 Oct 2019	Engine	1		1	
WoF Expiry:	03 Oct 2019	Odometer:	146,261 Kms	Good No:	18845344	Oil level	~			
VIN:	WBAVS12050KV96338	Next Service:	152000	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
						Performance	~			
Key:	S	-0		-161-		Radiator / Hoses (visual)	~			
S = scratch						Transmission	mission			
D = dent						Operation	~			
R = rust PT = paint defe				$\prod$		Noise	~			
C = crack				$+ \vee$		Clutch	-		~	
P = pin dent					세비	CV joints			~	
* = decals	616			The	ELL'S	Wheel bearings	~			
SC = stone chips						Brakes			L	
W = significant	t scuffs		S S		S	Performance	~			
Dealerteen		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread depth of tyres)			es)	
Stone chips front screen.									mm	
						Right front	e		mm	
						Left rear			mm	
Conditions During Body Inspection: Dry						Right rear		7 m		
Conditions During Body Inspection: Dry						Spare	, N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
RWD.						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	-			
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets	0000					Indicators	~			
Panels	Good					Dashboard warning lights	~		+	
	Good					Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
	1					Window winder FR	~			
General Comments					Window winder RL	~		+		
						Window winder RR	~		<u> </u>	
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2		1	
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~		+	
Engine Tir	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			<b>v</b>	
Inspected	Inspected by: Eddie Marsters Date: 10 Dec 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....