

Basic Vehicle Condition Guide

Report ID: 18,846,204

Pass

~

~

/

V

1

Tyres (lowest observed tread depth of tyres)

Version: 2

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Suspension performance Steering performance

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Operation

Head lights Tail lights Indicators

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 21 Dec 2018

Fail

N/A

1

mm

mm

mm

 mm

3

6


1

Yes

Make: Model: Chery J11 **Body Style:** SUV Year: 2014 Registration: HHS573 **Reg Expiry:** 17 Mar 2019 WoF Expiry: **Odometer:** 04 Jan 2020 47,612 Kms **Good No:** 18846204 VIN: LVVDB24B4CD273111 Next Service: 56,000kms **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Windscreen stone chips

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

	_
Conoral	Comments
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Name:

Wipers (front & rear)	>				
Window winder FL	>				
Window winder FR	~				
Window winder RL	~				
Window winder RR	~				
Rear view mirrors	~				
Radio (basic test only)	>				
CD (basic test only)	~				
Number of keys	2				
Central locking	~				
Remote locking	~				
Sat. Nav. (basic test only)			~		
Reversing camera			~		
Date: 21 Dec 2018					
Signature:					

inspected by:	Ca mach	Date:	21 Dec 2016