

Report ID: 18,847,779 Version: 1 12 Dec 2018 Created:

| Make: | Holden | Model: | Commodore | Body Style: | Wagon | | Pass | Fail | N/A |
|--|---------------------------|----------------------|----------------------|----------------------|----------------------|--|------|------|-----|
| Year: | 2002 | Registration: | AQA979 | Reg Expiry: | 04 May 2019 | Engine | | | |
| WoF Expiry: | 03 May 2019 | Odometer: | 175,999 Kms | Good No: | 18847779 | Oil level | ~ | | |
| VIN: | 6H8VXL35F2L851516 | Next Service: | 181000 | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | eration is made | for age and milear | ne Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechar | lical inspection prior to | purchase and t | his can be arranged | for an additional of | charge. | Coolant condition | ~ | | |
| | S | | S | | | Performance | r | | |
| Key: | L. L | -0 | | 502- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | 1 | | |
| D = dent R = rust | s dia | | | 710 | HIVS | Operation | ~ | | |
| PT = paint def | ect NP | r I | | | 7014 | Noise | r | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | HIG | | | | 74116 | CV joints | ~ | | |
| * = decals | s die | | | | ELC'S | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs S S S S S | | | | | | Performance | ~ | | |
| Podylog | action Commonts | Note: son | ne defects & blemish | nes may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments Ac not cold | | | | | | Tyres (lowest observed tread depth of tyres) | | | es) |
| Ac hot cold Minor Oil leaks engine/trans/diff | | | | | | Left front 5.0 m | | | mm |
| | | | | | | Right front | | .0 | mm |
| | | | | | | Left rear | 2 | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | | | mm |
| | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| Brakes soft | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | V | | |
| | | | | | | Shock absorbers | V | | |
| | | | | | | Air Conditioning / Heater | 1 | | |
| | | | | | | Operation | V | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| | Average | | | | | Tail lights | ~ | | |
| Carpets | / Weitage | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| | Average | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ird | | | | | Window winder FL | ~ | | |
| | ľ | | | | | Window winder FR | ~ | | |
| General Comments | | | | | | Window winder RL | ~ | | |
| Brakes noisy | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | 1 | • |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | • | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| | | | | | | | | | |
| Inspected by: Jeff Luke Date: 11 Dec 2018 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: