

Report ID: 18,848,677 Version: 1 10 Dec 2018 Created:

Make:	BMW	Model:	3 Series	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2006	Registration:	HHA694	Reg Expiry:	20 Aug 2019	Engine		-	<u> </u>	
WoF Expiry:		Odometer:	105,807 Kms	Good No:	18848677	Oil level	~			
VIN:	WBAVA76080NK6487	Next Service:		Service Histor		Smoke & fumes	~			
						Performance	~			
	port is not a warranty					Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition				
		_				Performance	~			
Key:		-0			s	Radiator / Hoses (visual)	~			
S = scratch	STE	A CO		10c	X	Transmission	V			
D = dent	IS ALS			The	BIDS	Operation	~		<u> </u>	
R = rust				10	7HIX —	Noise	~			
PT = paint defe C = crack	ect			+		Clutch	~			
P = pin dent	Ho								~	
* = decals	MIC					CV joints Wheel bearings			~	
SC = stone chi	ps US	VA		10			~			
W = significant scuffs S S S W S P						Brakes				
		Nata				Performance	~		<u> </u>	
<u>Body Insp</u>	pection Comments	Note: som	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake			Ļ	
Bonnet struts poor						Tyres (lowest observed tread depth of tyres)				
						Left front	7		mm	
						Right front	7		mm	
						Left rear	6	5	mm	
Conditions During Body Inspection: Dry						Right rear	6 mm			
Under Carriage & Under Bonnet Inspection Comments					Spare	No				
	image & Under Bor	inet inspectic	on comments			Suspension				
Clean						Suspension performance	~		<u> </u>	
						Steering performance	~		<u> </u>	
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments Good						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpets	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
Deal-L	Good					Wipers (front & rear)	~			
Dashboa	iiu					Window winder FL	~			
						Window winder FR	~			
<u>General C</u>	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
•	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected	Inspected by: Stuart Melbourne Date: 10 Dec 2018									

I have read and understood this condition guide.

Name:

Signature: