

Basic Vehicle Condition Guide

Report ID: 18,849,441


Version: 1

Created: 12 Dec 2018

Make: Model: Holden Colorado **Body Style:** Utility Year: 2014 Registration: HJA615 Reg Expiry: 06 Jul 2019 WoF Expiry: **Odometer: Good No:** 12 Apr 2019 221,089 Kms 18849441 VIN: MMU148MK0EH62413 **Next Service:** 225000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Service due

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jeff Luke Date: 11 Dec 2018

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	v v		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>V</i>		
Radiator / Hoses (visual)	~		
Transmission	ı		
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	<u>.</u> es)
Left front		.0	mm
Right front		.0	mm
Left rear		.0	mm
Right rear	3.0		mm
Spare		Yes	
Suspension		103	
Suspension performance	/		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	V		
Tail lights	<i>'</i>		
Indicators	~		
Dashboard warning lights	<i>'</i>		
Wipers (front & rear)	V V V V V		
Window winder FL	•		
Window winder FR	•		
Window winder RL	•		
Window winder RR	•		
Rear view mirrors	•		
Radio (basic test only)	V		
CD (basic test only)	2		
Number of keys	2		
Central locking	-		
Remote locking			<u> </u>
Sat. Nav. (basic test only)			'
Reversing camera		<u> </u>	<u> </u>
Date: 11 Dec 20	10		

Signature: