

Basic Vehicle Condition Guide

Report ID: 18,849,867


Version: 1

Created: 12 Dec 2018

Make: Model: Mazda CX-7 **Body Style:** Wagon Year: 2007 Registration: DZW438 Reg Expiry: 17 Jan 2019 **Odometer:** WoF Expiry: 14 Apr 2019 144,577 Kms **Good No:** 18849867 VIN: JM0ER103100105574 Next Service: 151057 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Windscreen stone chips

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Only one remote key working Underbody oxidisation

| Interior Comments | | | |
|-------------------|---------------------------------|--|--|
| Seats | Drivers seat torn | | |
| Carpets | Average | | |
| Panels | Right rear door panel scratched | | |
| Dashboard | Dashboard scratched | | |

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

12 Dec 2018 Inspected by: John Lindsay Date:

Name:

| | _ | | |
|------------------------------|--------------|---------|----------|
| | Pass | Fail | N/A |
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | <i>v</i> | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | | 4 | mm |
| Right front | 4 | | mm |
| Left rear | | 7 | mm |
| Right rear | 7 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | ! | | - |
| Operation | ~ | | |
| Electrical / Accessories | I | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | \(\times \) | | |
| Wipers (front & rear) | <i>v</i> | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | V | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | |
| Central locking | · | | |
| Remote locking | <u></u> | | |
| Sat. Nav. (basic test only) | ļ - | | 1 |
| Reversing camera | | | <i>y</i> |
| eversing cumera | | | |

Signature: