

Report ID: 18,850,585 Version: 2 07 Feb 2019 Created:

Make:	lsuzu	Model:	D-MAX	Body Style:	Utility		Pass	Fail	N/A
Year:	2016	Registration:	JZB872	Reg Expiry:	20 Jul 2019	Engine			
WoF Expiry:	07 Dec 2020	Odometer:	67,569 Kms	Good No:	18850585	Oil level	V		
VIN:	MPATFR85JGT000795	Next Service:	70,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	r		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	nical inspection prior to	purchase and tl	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	ls	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission	-		
D = dent	s 6/6			The		Operation	~		
R = rust PT = paint def				í In	JHIH	Noise	~		
C = crack					S S	Clutch			~
P = pin dent						CV joints			~
* = decals	ssc 916			- AL	ETTPS-	Wheel bearings	~		•
SC = stone chips						Brakes			
W = significant scuffs S S P S S P S						Performance	~		
		Note: son	he defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed treat		oftyre	
LH foot step front end broken RL seat head rest missing									
	a . est					Right front			mm
						Left rear	6		mm
	<u> </u>		_			Right rear			-
Conditions During Body Inspection: Dry						-			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Engine oil leak minor						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation			
Interior Comments						•			
Average						Electrical / Accessories Head lights			
Seats							~		
Carpets	Average					Tail lights Indicators	v		
	Good						v		
Panels						Dashboard warning lights	v		
Dashboa	rd Good					Wipers (front & rear) Window winder FL	v		
						Window winder FL Window winder FR	v		
General (<u>Comments</u>					Window winder FR Window winder RL	~		
							V 		
						Window winder RR	v		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only) Number of keys	~		
						-	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
				11113.		Reversing camera	~		
Inspected by: Mathew Varghese Date: 07 Feb 2019									

I have read and understood this condition guide.

Name:

Signature: