

Turners Certified Imports 50 Point Check

Report ID: 18,850,846

Version: 1

Created: 13 Dec 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:ToyotaBody Style:WagonModel:MarkxOdometer:94,896 KmsYear:2013VIN:7AT0H64TX18042163

Under Carriage & Under Bonnet Inspection Comments

General Comments

Seats: Average

Carpets: Average

Panels: Average

Dashboard: Average

Engine Timing Mechanism:


Evidence of Cam Belt Replacement:


Not Applicable

Replaced At (odometer reading):


Road Conditions During Test Drive: Dry

Electrical Battery Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Reversing camera •





Inspected by: Greg Morgan



Date: 13 Dec 2018