

Report ID: 18,851,398 Version: 1 21 Dec 2018 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2013	Registration:	HEQ737	Reg Expiry:	18 Jul 2019	Engine	1		1
WoF Expiry:	05 Dec 2019	Odometer:	242,720 Kms	Good No:	18851398	Oil level	~		
VIN:	MMU148FK0EH60628	Next Service:	Just Serviced	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
			S			Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust	SD D			210	HIV SD	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74 <u>11</u> 4	CV joints	~		
* = decals	s alt			The second	ELC'S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan			S S			Performance	~		
Body Incr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	8.	.0	mm
						Right front	8.	.0	mm
						Left rear	8.	.0	mm
Conditions During Body Inspection: Dry						Right rear	8.	8.0 mm	
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Comoto	Average					Tail lights	~		
Carpets						Indicators	<		
Panels	Average					Dashboard warning lights	~		
D!!	Average					Wipers (front & rear)	~		
Dashboa	iiu j					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	۲		
						Window winder RR	2		
						Rear view mirrors	~		
						Radio (basic test only)	2		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	۲		
Г			-			Remote locking	2		
-	ming Mechanism:	Timing (Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Increate						Date: 13 Dec 20	18		
Inspected by: Jeff Luke Date: 13 Dec 2018									

I have read and understood this condition guide.

Name:

Signature: