

Report ID: 18,852,497 Version: 2 15 Jan 2019 Created:

Make:	Toyota	Model:	Aurion	Body Style:	Sedan		Pass	Fail	N/A
Year:	2008	<b>Registration:</b>	EMJ621	<b>Reg Expiry:</b>	15 Dec 2018	Engine	1		L
WoF Expiry:	14 Jan 2020	Odometer:	167,757 Kms	Good No:	18852497	Oil level	~		
VIN:	6T153KK400X305764	Next Service:	-	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for ago and miloag	o Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		$\neg$	PT D		Р	Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent	s sc				EII SP	Operation	~		
R = rust					JHIH	Noise	~		
PT = paint def C = crack				+		Clutch			~
P = pin dent	Htc					CV joints	~		
* = decals	sc gig				ELIP PT	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S S									1
							~		
<u>Body Insp</u>	pection Comments	Note: son	le délècts à blemisne	es may not be disp	played in the diagram	Hand Brake			
Remote locking faulty						Tyres (lowest observed tread depth of tyres)			
						Left front		5	mm
						Right front		5	mm
						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear	3 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
<u>Under Ca</u>	irriage & Under Bor	inet inspectic	on Comments			Suspension		1	
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater		1	
Interior Comments						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
D!!	Good					Wipers (front & rear)	~		
Dashboa	ira					Window winder FL	~		
						Window winder FR	~		
<u>General</u> (	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	1	L
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking		~	
Engine Ti	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)		-	~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspecto	d by: Ca Thach					Date: 15 Jan 20	19		
inspecte	a by. Ca mach								

I have read and understood this condition guide.

Name: .....

Signature: .....