

Report ID: 18,853,330 Version: 1 01 Feb 2019 Created:

Make:	Nissan	Model:	Elgrand	Body Style:	SUV		Pass	Fail	N/A
Year:	2005	Registration:	HFP806	Reg Expiry:	04 Jul 2019	Engine	1	I	I
WoF Expiry:		Odometer:	182,751 Kms	Good No:	18853330	Oil level	~		
VIN:	7AT0DH6MX1300038!	Next Service:	Just Serviced	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	unting in the	for one code th	Danta har	hoon diseased a	Noise	~		-
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	S	-0	S S		s	Radiator / Hoses (visual)	~		
S = scratch	STE	A CO			XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Transmission	•		
D = dent	5 6/6			the	EIN S*	Operation	~		
R = rust				10	THIA	Noise	~		
PT = paint defe C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		
* = decals	s pip			AL.	EIP s*	Wheel bearings	~		
SC = stone chi	os US	VA		A		Brakes	V		
W = significant	scuffs S	-	S S		S*	Performance	~		
		Noto: com	ne defects & blemishes			Hand Brake			
Body Insp	ection Comments	Note: son	le délects & biemisnes	may not be disp	layed in the diagram		<ul> <li></li> </ul>		
Ac not cold						Tyres (lowest observed tread depth of tyres)			
						Left front		3	mm
						Right front		3	mm
						Left rear		-	mm
Conditions During Body Inspection: Dry						Right rear	-		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	mage & onder bor	inet inspectic	<u>In comments</u>			Suspension			
Shocks soft						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation		~	
Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
						Window winder FR	~		
General C	<u>comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
			•			Remote locking	~		
-	ning Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Jeff Luke Date: 18 Dec 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....