

Basic Vehicle Condition Guide

Report ID: 56,180

Version: 2

Engine

Created: 19 Dec 2018

Pass


N/A

Fail

Make: Model: FIT Honda **Body Style:** Hatchback Year: 2007 Registration: JHY120 **Reg Expiry:** 10 May 2019 WoF Expiry: **Odometer:** 01 Jan 2020 141,049 Kms **Good No:** 18853348 VIN: 7AT08G2YX15002408 **Next Service:** 151099 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>	
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Oil level Smoke & fumes 1 Performance / Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch J CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm 5.0 Right front 5.0 mm Left rear 4.0 mm Right rear 4.0 mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) 1 Reversing camera 1

Signature:

18 Dec 2018 Inspected by: Date:

Name: