

Basic Vehicle Condition Guide

Report ID: 18,855,256

Version: 1


18 Dec 2018 Created:

Fail N/A

Make: Model: Mitsubishi Lancer **Body Style:** Wagon Year: 2001 Registration: GCL853 Reg Expiry: 13 Apr 2019 **Odometer:** WoF Expiry: 28 Apr 2019 207,806 Kms **Good No:** 18855256 VIN: 7AT0CJ0DX11005872 **Next Service:** 201000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Minor stone chips front screen. No rear seat has been converted to a bed. Tailgate badge missing. Spare wheel not checked unable to gain access. Remote keypad totally worn out. Front ashtray missing

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine cover missing

| Interior Comm | <u>ents</u> |
|---------------|-------------|
| Seats | Average |
| Carpets | Average |
| Panels | Good |
| Dashboard | Good |

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

| Engine | | | |
|------------------------------|--|---------|----|
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | V | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | > | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | depth | of tyre | s) |
| Left front | | 4 | mm |
| Right front | | 4 | mm |
| Left rear | | 2 | mm |
| Right rear | | 5 | mm |
| Spare | | N/A | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | \(\times \) \(\t | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | | ~ | |
| CD (basic test only) | | ~ | |
| Number of keys | 1 | 1 | |
| Central locking | ~ | | |
| Remote locking | | ~ | |
| Sat. Nav. (basic test only) | | | ~ |

18 Dec 2018

Reversing camera