

Report ID: 18,857,443 Version: 2 01 Apr 2019 Created:

Signature: .....

Make:	Toyota	Model:	Hiace	Body Style:	Van		Pass	Fail	N/A
Year:	1998	Registration:	WX7109	Reg Expiry:	11 Mar 2020	Engine			
WoF Expiry:		Odometer:	58,878 Kms	Good No:	18857443	Oil level	~		
VIN:	7A421UHB308005699		50,070 14115	Service Histor		Smoke & fumes	~		
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					Performance	~		
	port is not a warranty		<i>.</i>			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:		-0			R	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent SCW SDR						Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack	ect III			+	R	Clutch	-		<u> </u>
P = pin dent	Ho				JUII ——	CV joints	~		~
* = decals	RPSC PIC			AL-	ETTR R	Wheel bearings	~		~
SC = stone chips						Brakes			<u> </u>
W = significan	t scuffs	- 0				Performance			
		Noto: com	ne defects & blemishes			Hand Brake	~		├───
<u>Body Ins</u>	pection Comments	Note. son	le délects & blemisnes	illay not be disp	layed in the diagram				
						Tyres (lowest observed tread depth of tyres)			
						Left front	3		mm
						Right front		3	mm
						Left rear		5 mn	
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	-	metmspectic	in comments			Suspension			
Underbody	surface rust					Suspension performance	~		<b> </b>
						Steering performance	~		<b> </b>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation			~
Poor						Electrical / Accessories			
Seats						Head lights	~		<b> </b>
Carpets	Average					Tail lights	~		<b> </b>
	Average					Indicators	~		<b> </b>
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		<b> </b>
						Window winder FL	~		<b> </b>
Concret	ommonts					Window winder FR	~		<b> </b>
General C Audio missi	<u>Comments</u>					Window winder RL	~		<b> </b>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)		~	<b> </b>
						CD (basic test only)		~	
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		<u> </u>
En aliz - T'	ming Masheritan	T:	<sup>°</sup> hain			Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
lun au	d by: Donovan Matar	2				Data: 01 Apr 20	10		
Inspecte		u				Date: 01 Apr 20	17		

I have read and understood this condition guide.

Name: .....