

## **Basic Vehicle Condition Guide**

Report ID: 18,859,185


Version: 1

Created: 20 Dec 2018

Make: Model: Honda Accord **Body Style:** Sedan Year: 2007 Registration: EGA729 Reg Expiry: 17 Jun 2019 WoF Expiry: **Odometer:** 17 Nov 2019 228,048 Kms **Good No:** 18859185 VIN: MRHCM66806P03069 Next Service: 206150 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Windscreen stone chips

Right front and rear plus left rear inner edge wear

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments			
Seats	Marks on drivers seat		
Carpets	Average		
Panels	Scratches on right rear panel		
Dashboard	Average		

## **General Comments**

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt

John Lindsay

**Evidence of Cam Belt Replacement:** Yes Kms: 205,728

Create	Created: 20 Dec 2018			
	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	\( \triangle \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	V			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes		Г	1	
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front		3	mm	
Right front	:	3	mm	
Left rear	3		mm	
Right rear	4		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	V V			
Shock absorbers	-			
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories				
Head lights	•			
Tail lights	\( \times \)			
Indicators	•			
Dashboard warning lights				
Wipers (front & rear)  Window winder FL	<b>V</b>			
Window winder FR	\( \triangle \)			
Window winder RL	,			
Window winder RR	<i>V</i>			
Rear view mirrors	V			
	<b>V</b>			
Radio (basic test only)	1			
CD (basic test only)  Number of keys	2			
	2			
Central locking  Remote locking	<b>V</b>			
Sat. Nav. (basic test only)			.,	
			.,	
Reversing camera				

I have read and understood this condition guide.

Name: .....

Signature: .....

20 Dec 2018

Date: