

Report ID: 18,860,841 Version: 3 09 Feb 2019 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2014	Registration:	HGQ259	Reg Expiry:	25 Jul 2019	Engine			
WoF Expiry:	22 Feb 2020	Odometer:	260,092 Kms	Good No:	18860841	Oil level	~		
VIN:	MNTCPGD22A000093	Next Service:	256000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	D	-0	S SR	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	S SC			715	SD SD	Operation	~		
PT = paint defe		F		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch	~		
P = pin dent	LEAT DECIDENCE				2414	CV joints			~
* = decals	S PT P SC PF			The second	ELD'S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan	S				S	Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
					Left front	ç	9	mm	
						Right front	ģ)	mm
						Left rear	e	5	mm
Conditions During Body Inspection: Wet						Right rear	6 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Underbody	surface rust					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Compete	Poor					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Darkh	Average					Wipers (front & rear)	~		
Dashboa	iiu y					Window winder FL	~		
	_					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	<		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
	mina Masharitar	T :	^c hoin			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Ca Thach Date: 09 Feb 2019									

I have read and understood this condition guide.

Name:

Signature: