

Report ID: 18,861,356 Version: 1 24 Dec 2018 Created:

Make:	BMW	Model:	M5	Body Style:	Sedan		Pass	Fail	N/A
Year:	2005	Registration:	JFR581	Reg Expiry:	13 Apr 2019	Engine			1
WoF Expiry:	20 Dec 2019	Odometer:	111,049 Kms	Good No:	18861356	Oil level	~		
VIN:	WBSNB92040BE18546	Next Service:	,	Service Histor		Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		C 1 11			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch	RE	A U			The second	Transmission	•		<u> </u>
D = dent	PT SC					Operation	~		
R = rust PT = paint def					JHH	Noise	~		
C = crack				$+ \mathbb{N}$		Clutch			~
P = pin dent					세비	CV joints			~
* = decals	sc 916				ELLAR	Wheel bearings	~		
SC = stone chi		26	\Box	20	¥ —	Brakes	•		L
W = significan	t scuffs	$- \emptyset$	S	- Vr		Performance	~		
		Note: som	e defects & blemishe	es may not be disc	layed in the diagram	Hand Brake	~		
Body Insp	pection Comments					Tyres (lowest observed treat	-	oftvre	 >s)
						Left front 6 mm			
						Right front		5	 mm
						Left rear			mm
						Right rear			
Conditions During Body Inspection: Dry						Spare	6 mm		
Under Carriage & Under Bonnet Inspection Comments						Suspension	No		
Clean						Suspension performance	~		
cicuit						Steering performance			<u> </u>
						Shock absorbers	~ ~		<u> </u>
						Air Conditioning / Heater	V		
						J			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats						Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		<u> </u>
	Good					Indicators	~		<u> </u>
Panels						Dashboard warning lights	~		<u> </u>
Dashboa	Good Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
General	omments					Window winder FR	~		<u> </u>
General Comments Rattle in engine very hard to trace source						Window winder RL	~		──
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		──
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	2	-	·
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		<u> </u>
Engine Ti	ming Mechanism	Timing	- bain			Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		<u> </u>
Evidence	ог сант вен керіас	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspecte	d by: Stuart Melbourr	ne				Date: 24 Dec 20	18		
						24.6. 2.26620	-		

I have read and understood this condition guide.

Name:

Signature: