

Basic Vehicle Condition Guide

Report ID: 18,861,715


Version: 1

Created: 24 Dec 2018

Make: Model: Toyota Aristo **Body Style:** Sedan Year: 1998 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 03 Mar 2019 62,379 Kms 18861715 VIN: 7AT0H627X18011482 **Next Service:** Unknown **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Twin turbo

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Murray Craig Date: 24 Dec 2018

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	\(\times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints			~	
Wheel bearings	~			
Brakes		•		
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front		7	mm	
Right front	7		mm	
Left rear	4		mm	
Right rear	3		mm	
Spare		Yes		
Suspension	•			
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories			•	
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	V V V V			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1			
Central locking	~			
Remote locking			~	
Sat. Nav. (basic test only)			~	
Reversing camera			~	

Signature: