

Report ID: 18,861,727 Version: 1 27 Dec 2018 Created:

Make:	Volkswagen	Model:	Passat	Body Style:	Wagon		Pass	Fail	N/A
Year:	2005		FRP860	Reg Expiry:	10 May 2019	Engine			
WoF Expiry:		Odometer:	156,627 Kms	Good No:	18861727	Oil level	~		1
VIN:	WVWZZZ3BZ5E13506		150,027 14115	Service Histor		Smoke & fumes	~		
	WWWEELSDESE 15500					Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:	s w	0	S S PT			Radiator / Hoses (visual)	~		
S = scratch D = dent SC						Transmission			
						Operation	~		
R = rust				TIO	7HIH	Noise	~		-
PT = paint def C = crack	ect			+		Clutch	~		
P = pin dent	Ho				االلا	CV joints	~		~
* = decals	sc pp					Wheel bearings	-		
SC = stone chi	ps US	LA		10	& <u> </u>	<u>_</u>	~		
W = significant scuffs W S						Brakes			Т
						Performance	~		
Body Ins	pection Comments	Note: som	ie delects & biemisne	es may not be disp	layed in the diagram	Hand Brake		<u> </u>	
LR lens cracks					Tyres (lowest observed tread depth of tyres)				
						Left front		2	mm
						Right front		2	mm
						Left rear	4	4	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
Under Carriage & Under Bonnet Inspection Comments					Spare Yes				
	image & Under Bor	inet inspectic	on Comments			Suspension			
Dirty						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
linterior C	o no no o no to					Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dachhar	Good					Wipers (front & rear)	~		
Dashboa	iru					Window winder FL	~		
	_					Window winder FR	~		
General (	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)		~	
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		1
-	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
							1	1	
Inspecte	d by: Stuart Melbourr	ne				Date: 27 Dec 20	18		

I have read and understood this condition guide.

Name: .....

Signature: .....