

Basic Vehicle Condition Guide

Report ID: 18,862,945


Version: 1

Created: 04 Jan 2019

Make: Model: IS250 Lexus **Body Style:** Sedan Year: 2005 Registration: KDB105 Reg Expiry: 09 Feb 2019 WoF Expiry: **Odometer:** 06 Dec 2019 99,250 Kms **Good No:** 18862945 VIN: 7AT0B00EX16006474 **Next Service:** Due **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Service due.

RR window not working.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil level low.

| Interior Comments | | | | |
|-------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

| _ | _ |
|---------|----------|
| Conoral | Comments |
| General | COMMENTS |

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Scott Willoughby Date: 03 Jan 2019

| | Pass | Fail | N/A |
|------------------------------|---------------------------------------|---------|-----|
| Engine | • | • | |
| Oil level | | ~ | |
| Smoke & fumes | ~ | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | V V | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed treac | depth | of tyre | :s) |
| Left front | 4 | .0 | mm |
| Right front | 4.0 | | mm |
| Left rear | 4.0 | | mm |
| Right rear | 4 | .0 | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | ı |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | > > > > > > > > > > > > > > > > > > > | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | | ~ | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | 1 | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | ~ | | |
| | | 1 | |

I have read and understood this condition guide.

Name:

Signature: