

Report ID: 18,863,532 Version: 1 08 Jan 2019 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Sedan		Pass	Fail	N/A
Year:	2009	<b>Registration:</b>	LML354	<b>Reg Expiry:</b>	03 Jan 2019	Engine			
WoF Expiry:	04 Jul 2019	Odometer:	108,291 Kms	Good No:	18863532	Oil level	~		
VIN:	7AT0GF09X17002381	Next Service:	110000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
AL / 1911						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	lical inspection prior to	purchase and u	his can be arranged to	or an additional of	.narge.	Coolant condition	~		
			S S			Performance	V		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent	TE				An	Transmission		1	
B = uent R = rust	S PT			710	HILLS	Operation	~		
PT = paint def	ect NP					Noise	r		
C = crack					S	Clutch			~
P = pin dent	HIG			$\langle \rangle$	74114	CV joints	~		
* = decals	- Alt	10		10		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S S W						Performance	~		Τ
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		<u> </u>
Stone chips front screen.Spider marks on roof.						Tyres (lowest observed tread depth of tyres			
						Left front	3.5		mm
						Right front	2	.5	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear		4	mm
Conditions During Body inspection. Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			<u> </u>
Seats	Good					Head lights	~		T
	Good					Tail lights	~		+
Carpets						Indicators	~		+
Panels	Good					Dashboard warning lights	~		+
						Wipers (front & rear)	~		
Dashboa	Ird Good					Window winder FL	~		+
L	1					Window winder FR	~		+
General Comments					Window winder RL	~			
Overseas nav system.						Window winder RR	~		+
						Rear view mirrors	~		
						Radio (basic test only)	~		+
						CD (basic test only)	~		+
						Number of keys	1	I	L
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
						Remote locking		~	+
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
							1		
Inspected by: Eddie Marsters						Date: 08 Jan 201	9		
I have read	and understood th	is condition o	juide. Name:			Signature:			