

Report ID: 18,865,504 Version: 2 04 Feb 2019 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Sedan		Pass	Fail	N/A
Year:	2008	Registration:	EGR544	Reg Expiry:	01 Jul 2019	Engine			<u> </u>
	07 Dec 2019	Odometer:	274,048 Kms	Good No:	18865504	Oil level	~		
VIN:	JM0GG103200553282	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I II	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:	sc	-0	SD SDPT		S D	Radiator / Hoses (visual)	~		
S = scratch	STE	A CO			T	Transmission	•		
D = dent	sscw dla			1n-	SDPTCW	Operation	~		<u> </u>
R = rust				1 M	THIA	Noise	~		-
PT = paint defe C = crack	ect M			+	R SC	Clutch	~		~
P = pin dent	Ho				JUII ——	CV joints	~		
* = decals	DSC PR			AL-	EIRS	Wheel bearings	-		
SC = stone chi	ps US	LA		A		Brakes	~		
W = significant scuffs SR SC W SD SC D W SD						Performance			1
							~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Windscreen stone chips Rear bumper alignment left side						Tyres (lowest observed tread depth of tyres)			
Rear bumpe	er alignment lett side					Left front	5		mm
						Right front		5	mm
						Left rear		1	mm
Conditions During Body Inspection: Wet						Right rear	5 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	mage & onder bor	mermspectic	<u>In comments</u>			Suspension			. <u> </u>
Oil leak						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Holes and stains in rear seat, seats worn					Electrical / Accessories				
Seats	Holes and	stains in real sea	it, seats worn			Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
	_]	Window winder FR	2		
<u>General Comments</u>					Window winder RL	<			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: John Lindsay Date: 04 Feb 2019									

I have read and understood this condition guide.

Name:

Signature: