

Basic Vehicle Condition Guide

Report ID: 18,867,761


Version: 3

Created: 21 Jan 2019

Make: Model: Holden Adventra **Body Style:** SUV Year: 2006 Registration: DNT200 Reg Expiry: 11 Jan 2019 WoF Expiry: **Odometer: Good No:** 26 Jun 2019 269,159 Kms 18867761 VIN: 6G1ZM84786L871927 **Next Service:** 280000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy

Interior Commen	nts .
Seats	Good
Carpets	Average
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Stuart Melbourne Inspected by:

Pass V V V V V V V V V V V	Fail	N/A
<i>V V</i>		· ·
<i>V V</i>		
<i>V V</i>		
<i>V V</i>		· ·
<i>V V</i>		· ·
\(\times \) \(\t		·
ン ン ン ン ン		·
V V V V		v
\(\times \)		V
<i>V V V</i>		·
ン ン ン ン		<i>v</i>
<i>V V V</i>		~
v v		~
ν ν		
~		I
~		
~		
depth	of tyre	<u></u>
7.	.0	mm
7.	.0	mm
5.	.0	mm
5.	.0	mm
	Yes	
~		
~		
~		
v		
~		
~		
~		
-	~	
2	_	
<u>-</u>		
<u>,</u>		-
		/
		./
	depth 7 7 5 5 V	depth of tyre 7.0 7.0 5.0 5.0

I have read and understood this condition guide.

Name:

Signature:

20 Jan 2019

Date: