Turners Certified Imports 50 Point Check

Report ID: 18,868,347
Version: 1
Created: 11 Jan 2019

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Mazda	Body Style:	Hatchback
Model:	Axela	Odometer:	33,633 Kms
Year:	2007	VIN:	7AT0C13JX19320028

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

Under Carriage & Under Bonnet Inspection Comments

/

General Comments

/

Engine Timing Mechanism:	Timing Chain
Evidence of Cam Belt Replacement:	Not Applicable
Replaced At (odometer reading):	
Road Conditions During Test Drive:	Dry

Electrical

Battery	✔
Head lights	✔
Tail lights	✔
Indicators	✔
Dashboard warning lights	✔
Wipers (front & rear)	✔
Window winder FL	✔
Window winder FR	✔
Window winder RL	✔
Window winder RR	✔
Rear view mirrors	✔
Radio (basic test only)	✔
CD (basic test only)	✔
Reversing camera	•

Transmission & Drive

Operation	✔
Noise	✔
Clutch	•
CV joints	✔
Wheel bearings	✔
Wheel balance	✔

Brakes

Performance	✔
Hand Brake	✔

Keys & Locking

Central locking	✔
Remote locking	✔
Number of keys	2

Engine

Oil level	✔
Smoke & fumes	✔
Performance	✔
Noise	✔

Cooling System

Coolant condition	✔
Performance	✔
Radiator / Hoses (visual)	✔

Suspension

Suspension performance	✔
Steering performance	✔
Shock absorbers	✔

Tyres (lowest observed tread depth)

Left front	8.0	mm
Right front	8.0	mm
Left rear	8.0	mm
Right rear	8.0	mm
Spare	Yes	
Tools		

Interior

AC Operation	✔
Heater fan	•
Seatbelts	✔
Horn	✔

Turners Certified Key
✔ = Pass ✘ = Fail
• = Not applicable for this vehicle

Inspected by: Chris Buckley Date: 11 Jan 2019

I have read and understood this condition guide. Name: ..... Signature: .....