

Report ID: 18,869,583 Version: 2 23 May 2019 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2013	<b>Registration:</b>	GSZ502	Reg Expiry:	10 Sep 2019	Engine			
WoF Expiry:	29 Jan 2020	Odometer:	141,799 Kms	Good No:	18869583	Oil level	~		
VIN:	MNTVCUD40A002632	Next Service:	151739	Service Histor	y: No	Smoke & fumes	~		
Net TI						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
		purchase and ti	lis can be analiged to		narge.	Coolant condition	~		
	S SC	$\sim$	S P SC S P SC		S SC	Performance	~		
Key: S = scratch						Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch	~		
P = pin dent						CV joints	~		
* = decals SC = stone chips						Wheel bearings	~		
W - significant scuffs						Brakes			
	S P SC	$\sim$	S D SC S D SC		S P SC	Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Sports lid different colour.						Tyres (lowest observed tread depth of tyres)			
						Left front	6	.0	mm
						Right front	6	.0	mm
						Left rear	6	.0	mm
Conditions During Body Inspection: Dry						Right rear 6.0 mm			mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats	, weitige					Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
Gonoral	ommonts					Window winder FR	~		
General Comments Vehicle has recently had a replacement clutch and new Timing chains.						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Donovan Matara Date: 05 Feb 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....