

Report ID: 18,872,250 Version: 1 Created: 16 Jan 2019

Make:	Nissan	Model:	Cefiro	Body Style:	Wagon		Pass	Fail	N/A
Year:	1997	Registration:	BHD370	Reg Expiry:	31 Jan 2019	Engine	1	I	ı
WoF Expiry:	23 Jul 2019	Odometer:	224,714 Kms	Good No:	18872250	Oil level	~		
VIN:	7A8DH2A0703725046	Next Service:	211500	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	PS	-0		-01-		Radiator / Hoses (visual)	~		<u> </u>
S = scratch						Transmission	ransmission		
D = dent	SC DI			TIN	FIL S	Operation	~		
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+	PT	Clutch	-		~
P = pin dent					741L	CV joints	~		
* = decals	S PT SC 916		ĕ ─I⊢	- NL	ETT PT	Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs						Performance			
Note: come defecte % blomiches may not be displayed in the displayer						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	•	oftyre	<u> </u>
Hard to open bonnet Right wing mirror cover cracked						Left front			mm
						Right front		.6	-
						Left rear		3	mm
								4	mm
Conditions During Body Inspection: Dry						Right rear		3	mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Front tyre camber wear						Suspension			1
Front tyre c	amper wear					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation		~	
	Average					Electrical / Accessories			
Seats	Avelage					Head lights	~		
Carpets	Average					Tail lights	~		
curpets	A					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
<u> </u>						Window winder FR	~		
General Comments					Window winder RL	~			
AC not working Wing mirror cannot retract						Window winder RR	~		
Key need attention(one for ignition and one for door lock) Ignition cover broken						Rear view mirrors		~	
Ignition cov	ver broken					Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
			•			Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
La constant luca - Dalabar Zhang									
Inspected by: Bobby Zhong Date: 16 Jan 2019									
I have read a	and understood th	is condition c	uide. Name:			Signature:			