

Report ID: 18,872,968 Version: 1 29 Jan 2019 Created:

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass F	ail N/A
Year:	2013		HCE183	Reg Expiry:	26 May 2019	Engine	1 455	
WoF Expiry:		Odometer:	211,803 Kms	Good No:	18872968	Oil level	~	
VIN:	KMHST81XSDU16290			Service Histor		Smoke & fumes	~	
			221000			Performance	~	
	port is not a warranty					Noise	v v	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition		
				_		Performance	~	
Key:		-0	S S			Radiator / Hoses (visual)	v v	
S = scratch	Se	20		1000	X	Transmission	V	
D = dent	SDCW			1 - L	BID SW			
R = rust				10		Operation Noise	レ レ	
PT = paint defe C = crack	ect 1			+	SC SC	Clutch		
C = Crack P = pin dent	LHC	KI						
* = decals	sc pp			SI_	Ell'Asc	CV joints	~	
SC = stone chips						Wheel bearings	~	
W = significan	t scuffs	-	S SP			Brakes		
		Notorer			laved in the diagram	Performance		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		
Rear bumper and trim insecure					Tyres (lowest observed tread depth of tyres)			
						Left front	4.0	mm
						Right front	4.0	mm
						Left rear	6.0	mm
Conditions During Body Inspection: Wet					Right rear	6.0	mm	
					Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments Underside tray broken						Suspension		
Underside t	ray broken					Suspension performance	~	
						Steering performance	~	
						Shock absorbers	~	
						Air Conditioning / Heater		
Interior Comments						Operation 🖌		
Interior Comments Average						Electrical / Accessories		
Seats	Average					Head lights	~	
Carpets	Average					Tail lights	~	
						Indicators	~	
Panels	hood linin	y tear				Dashboard warning lights	~	
Dashboa	Average					Wipers (front & rear)	~	
Dashboa						Window winder FL	~	
						Window winder FR	~	
<u>General Comments</u>						Window winder RL	~	
						Window winder RR	~	
						Rear view mirrors	~	
						Radio (basic test only)	~	
						CD (basic test only)	~	
						Number of keys	2	
Road Conditions During Test Drive: Wet						Central locking	~	
	_					Remote locking	~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)		~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~	
Inspected by: Greg Morgan Date: 16 Jan 2019								

I have read and understood this condition guide.

Name:

Signature: