

Basic Vehicle Condition Guide

Report ID: 52,690


Version: 2

Created: 25 Jan 2019

Make: Model: X5 **BMW Body Style:** SUV Year: 2009 Registration: LUP25 Reg Expiry: 01 Sep 2019 **WoF Expiry: Odometer:** 10 Aug 2019 174,000 Kms **Good No:** 18873082 VIN: WBAFF420X0L180452 Next Service: 184000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

| Conditions During Boo | dy Inspection: |
|-----------------------|----------------|
|-----------------------|----------------|

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

DM Auto's 18 Jan 2019 Inspected by: Date:

| | Pass | Fail | N/A | | | |
|------------------------------|---------------------------------------|---------|----------|--|--|--|
| Engine | | | | | | |
| Oil level | ~ | | | | | |
| Smoke & fumes | ~ | | | | | |
| Performance | \(\triangle \) | | | | | |
| Noise | ~ | | | | | |
| Cooling System | | | | | | |
| Coolant condition | ~ | | | | | |
| Performance | <i>V</i> | | | | | |
| Radiator / Hoses (visual) | > | | | | | |
| Transmission | | | | | | |
| Operation | ~ | | | | | |
| Noise | ~ | | | | | |
| Clutch | | | ~ | | | |
| CV joints | ~ | | | | | |
| Wheel bearings | ~ | | | | | |
| Brakes | | | | | | |
| Performance | ~ | | | | | |
| Hand Brake | ~ | | | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | | | |
| Left front | 6 | .0 | mm | | | |
| Right front | 6.0 | | mm | | | |
| Left rear | 6.0 | | mm | | | |
| Right rear | 6 | .0 | mm | | | |
| Spare | | Yes | | | | |
| Suspension | | | | | | |
| Suspension performance | ~ | | | | | |
| Steering performance | ~ | | | | | |
| Shock absorbers | ~ | | | | | |
| Air Conditioning / Heater | | | | | | |
| Operation | ~ | | | | | |
| Electrical / Accessories | | | | | | |
| Head lights | ~ | | | | | |
| Tail lights | \(\times \) | | | | | |
| Indicators | ~ | | | | | |
| Dashboard warning lights | ~ | | | | | |
| Wipers (front & rear) | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | | | |
| Window winder FL | ~ | | | | | |
| Window winder FR | ~ | | | | | |
| Window winder RL | ~ | | | | | |
| Window winder RR | ~ | | | | | |
| Rear view mirrors | V | | | | | |
| Radio (basic test only) | • | | | | | |
| CD (basic test only) | • | | | | | |
| Number of keys | 2 | | | | | |
| Central locking | • | | | | | |
| Remote locking | ~ | | _ | | | |
| Sat. Nav. (basic test only) | | | ' | | | |
| Reversing camera | | | | | | |

I have read and understood this condition guide.

Name:

Signature: