

Basic Vehicle Condition Guide

Report ID: 18,873,547


Version: 1

Created: 25 Jan 2019

Make: Model: Mitsubishi Pajero **Body Style:** SUV Year: 2008 Registration: HGY19 Reg Expiry: 02 Dec 2019 **Odometer:** WoF Expiry: 06 Feb 2020 289,508 Kms **Good No:** 18873547 VIN: JMFLYV98W7J002973 Next Service: 309500 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection:

Left front flare needs a clip Left running boards dent

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

Dry

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

16 Jan 2019 Inspected by: **Brad Lucas** Date:

Name:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
•		
~		
~		
		~
~		
~		
~		
~		
d depth	of tyre	es)
6	.0	mm
6.0		mm
8		mm
8 mm		
Yes		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
1	1	-
~		
~		
		1
		~
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ

Signature: